Weathertzation Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH3087Work Order Type: WeatherizationAudit Name: 13013SH3087

CLIENT INFORMATION

Client ID: 13013SH3087

<u>AGENCY INFORMATION</u>

Client ID: 13013SH3087

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: WOOD, JIM Work Phone:
Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

DOE Weatherization Assistant Version 8.6.0 Page 1 of 5

Client ID: 13013SH3087

	Measure 1 Infilt	ration Redctn			Componer	its			Inspected
C	9. BLOCK GLAZEE STORM WEATH DOOR S	AND SEAL A/ C WINDO AND SEAL A/C WINDO O WINDOWS #6,7, AND WINDOWS) ERSTRIP FRONT, BAC GWEEP NEEDED ON B CE WINDOW UNIT #3 (OW UNIT C D 10. (REM CK,AND SIE ACK AND	OMPL OVE A	ETE IN WA .ND REINST ORS.	LL #9 (C	•	E)	
		·	,		Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	1					
2	Labor	Infiltration Reduction	Each	1					
C	Other Detail								
] []		
				Measur	e Sub Total:			Sub Total:	
	Measure 2 DWF	I Pipe Insulation WATER LINES 6FT EAG	CH HOT AI		Componer LD	nts			Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail						1		
		Measure Sub Total: Sub Total:							
	Field Notes:								

Work Order Bid (ID)

DOE Weatherization Assistant Version 8.6.0 Page 2 of 5

Measure 3 Flo	or Ins. R-19			Componen	ts F1		ı	Inspected
Comment ADD R	R-19 974 SQ FT (ORIGINA	AL HOUSI	≣)					
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	974					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	974					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 4 Wa	ıll Insulation			Componen	ts WL1,W	VL10,V	VL11,W	Inspected
Measure 4 Wa	Ill Insulation			Componen	L12,W	L2,WL	VL11,W 4	Inspected
				Componen		L2,WL	,	Inspected
Measure 4 Wa					L12,W	L2,WL	,	Inspected
				Componen Estimated	L12,W	L2,WL	,	Inspected
		Units	Qty		L12,W	L2,WL	3,WL4,	Inspected
Comment ADD R	R-13 1312 SQ FT	<i>Units</i> SqFt		Estimated	L12,W WL5,V	L2,WL VL6	3,WL4,	
Comment ADD R	P-13 1312 SQ FT Description / Comment Wall Insulation - Blown		Qty	Estimated	L12,W WL5,V	L2,WL VL6	3,WL4,	
Comment ADD R # Material / Labor 1 Insulation 2 Labor	Pescription / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown	SqFt	Qty 1312	Estimated	L12,W WL5,V	L2,WL VL6	3,WL4,	
Comment ADD R # Material / Labor 1 Insulation	Pescription / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown	SqFt	Qty 1312	Estimated	L12,W WL5,V	L2,WL VL6	3,WL4,	
Comment ADD R # Material / Labor 1 Insulation 2 Labor	Pescription / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown	SqFt	Qty 1312	Estimated	L12,W WL5,V	L2,WL VL6	3,WL4,	
Comment ADD R # Material / Labor 1 Insulation 2 Labor	Pescription / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown	SqFt SqFt	Qty 1312	Estimated	L12,W WL5,V	Qty	3,WL4,	
Comment ADD R # Material / Labor 1 Insulation 2 Labor	Pescription / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown	SqFt SqFt	Qty 1312	Estimated Unit Cost	L12,W WL5,V	Qty	Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Pescription / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown	SqFt SqFt	Qty 1312	Estimated Unit Cost	L12,W WL5,V	Qty	Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Pescription / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown	SqFt SqFt	Qty 1312	Estimated Unit Cost	L12,W WL5,V	Qty	Actual Unit Cost	

Measure 5 CO	Monitor is Needed			Componen	ts			Inspected
Comment INSTALI	2 CO.MONITORS							
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	CO monitor	Each	2					
2 Labor	Labor	Each	2					
Other Detail						,		
] []	Sub Total:	
			Measur	e Sub Total:		,	Sub Total:	
(Bas	or Barrier Needed ement/CrawIspace) FT TO INCLUDE REPL	ACE CRA	.WLSP.	Componen ACE DOOR		4X16)		Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Basement / crawlspace vapor barrier	SqFt	974					
2 Labor	Basement / crawlspace vapor barrier	SqFt	974					
Other Detail	•							
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	

Measure 7 Ref	rigerator replacement			Componen	ts		I	nspected
Comment REPLA	CE REFRIGERATOR 20	CU FT						
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Refrigerators	REPLACE REFRIGERATOR	Each	1					
2 Refrigerators	REPLACE REFRIGERATOR	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	

Client ID: 13013SH3087